

Monitoring ID	Date	O2_1	CO_1	H2S_1	LEL_1	VOC_1	Comment
2-8	3/18/2019	20.9	0	0	0	0	Deerwood business Park
2-10	3/18/2019	20.9	0	0	0	0	Burger King east 13th
2-7	3/18/2019	20.9	0	0	0	0	
2-9	3/18/2019	20.9	0	0	0	0	UA Pipe Fitters union
2-11	3/18/2019	20.9	0	0	0	0	
2-12	3/19/2019	20.9	0	0	0	0	Below plume
2-13	3/19/2019	20.9	0	0	0	0	Residential beneath plume
2-14	3/19/2019	20.9	0	0	0	0	Recreational park south edge of plume
2-16	3/19/2019	20.9	0	0	0	0	Residential beneath plume.
2-18	3/19/2019	20.9	0	0	0	0	ITC yard beneath plume
1-12	3/18/2019	20.9	0	0	0	0	
1-15	3/18/2019	20.9	0	0	0	0	
1-16	3/18/2019	20.9	0	0	0	0	
1-18	3/18/2019	20.9	0	0	0	0	
1-21 NPL US Oil Recovery Site	3/19/2019	20.9	0	0	0	0	Could not gain access to site due to locked gate. Air monitoring point take on perimeter of site at gate.
1-23 NPL Dixie Oil Processors site	3/19/2019	20.9	0	0	0	0	Monitoring point taken at site locked gate.
1-20, NPL Patrick Bayou site	3/19/2019	20.9	0	0	0	0	NPL site located within Oxy plant, air monitoring location as close as team 1 could get to the site before reaching controlled entryway.
AM01-4	3/18/2019	20.9	0	0	0	0	
AM01-5	3/18/2019	20.9	0	0	0	0	
AM01-6	3/18/2019	20.9	0	0	0	0	
AM01-7	3/18/2019	20.9	0	0	0	0	
AM01-8	3/18/2019	20.9	0	0	0	0	
AM01-9	3/18/2019	20.9	0	0	0	0	
AM01-15	3/18/2019	20.9	0	0	0	0	
AM01-14	3/18/2019	20.9	0	0	0	0	
AM01-13	3/18/2019	20.9	0	0	0	0	
AM01-12	3/18/2019	20.9	0	0	0	0	
AM01-11	3/18/2019	20.9	0	0	0	0	
AM01-10	3/18/2019	20.9	0	0	0	0	
AM01-10	3/18/2019	20.9	0	0	0	0	
2-15	3/19/2019	20.9	0	0	0	0	Residential beneath plume.
2-17	3/19/2019	20.9	0	0	0	0	Residential north edge of plume
1-11	3/18/2019	20.9	0	0	0	0	

1-14	3/18/2019	20.9	0	0	0	0	
1-13	3/18/2019	20.9	0	0	0	0	
1-10	3/18/2019	20.9	0	0	0	0	
1-17	3/18/2019	20.9	0	0	0	0	
1-19	3/18/2019	20.9	0	0	0	0	
1-22 NPL Harris Farley st	3/19/2019	20.9	0	0	0	0	Air monitoring point taken from the side of the road adjacent to landfill NPL site.
1-24 NPL Brio Refining site	3/19/2019	20.9	0	0	0	0	Monitoring point collected across the road from the site due to availability of parking. Gate locked.
AM01-17	3/18/2019	20.9	0	0	0	0	
AM01-16	3/18/2019	20.9	0	0	0	0	
1-25 NPL site Geneva Industries/Furham Energy	3/19/2019	20.9	0	0	0	0	Could not directly access NPL site due to road closure.
1-26 NPL Site Sol Lynn/ Industrial Transformers.	3/19/2019	20.9	0	0	0	0	
1-32 NPL site Highlands Acid pit	3/19/2019	20.9	0	0	0	0	Could not access site.
1-33 NPL site San Jacinto River Waste Pits	3/19/2019	20.9	0	0	0	0	Could not access site
1-27 NPL Many Diversified Interests site	3/19/2019	20.9	0	0	0	0	
1-27 NPL site South Cavalcade st	3/19/2019	20.9	0	0	0	0	Could not access site directly
1-29 NPL site North Cavalcade st	3/19/2019	20.9	0	0	0	0	Could not access site. Monitoring at road adjacent to site.
1-30 NPL site Sikes Disposal Pits	3/19/2019	20.9	0	0	0	0	Gate to site locked, monitoring point taken at gate.
1-31 NPL site French Ltd.	3/19/2019	20.9	0	0	0	0	